

Received by Chief Ship Surveyor

16.6.13

Received from Chief Ship Surveyor

VESSEL'S NAME

Steelss Gracchus

Rpt.

Cal

No.

3156

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

DAMAGE.

Damage through

Grounding.

now repaired as follows:-

	Plates	Frames	R.Frames	Floors	Beams	Str.	Plates	Dk.	Plates
Renewed									
Removed and faired or repaired.....									
Faired or repaired in place.....									

Other items:-

Vessel examined in dry dock, bottom found to be unimpaired & afterwards cleaned & coated.

It is submitted the vessel is worthy to remain as classed with record of Survey 5.13 as recommended

100 A-1. Shell Dr.

5.13 Cal -



Lloyd's Register
Foundation