



# Lloyd's Register of Shipping,

97 & 98, Scottish Provident Buildings,  
Donegall Square, West,  
Belfast, 8th. September, 1919.

LLOYD'S REGISTER,  
LONDON.

REC'D 10 SEP 1919  
ANSD

Reference

M.

The Secretary,  
L o n d o n.

Sir,

I beg to acknowledge receipt of your letter of the 5th instant respecting the First Entry Report No. 8197 on the Steel Screw Steamer "NEW MEXICO", and with regard thereto I have to state that the arms of the Cast Steel Rudder are fitted **at** and between the rudder pintles on this vessel, the hand pumps as fitted are in efficient working order, and the margin angles on the tank top should be 7.5, as in the sister vessels.

I regret that this item was incorrectly reported.

I am, Sir,

Your obedient Servant,

*S. Kendall*



© 2021

Lloyd's Register  
Foundation

W147-0091

W147-001

Referred to the Chief Ship Surveyor.

*M.H.*

SEP 10 1899

Also for Mr. S. A. Hill to note.

*M*  
1899



© 2021

Lloyd's Register  
Foundation

Net Tonnage  
Tonnage on Beam

Angles on upper