

COPY.

Lloyd's Register of British & Foreign Shipping,

71, Fenchurch Street, E.C.

15th May, 1912.

Gentlemen,

E. With reference to Hull first entry machinery report No. 24990 in the case of the steamer "HONDO", I have to acquaint you that it is concluded that two main bearing bolts have been placed on board as spare, but as no mention is made of them in your report, I have to request that you will let me know whether this is so.

I am, Gentlemen,

Your obedient Servant,

Secretary.

The Surveyors,

H U L L.



© 2021

Lloyd's Register
Foundation