

Engines made at  
Boilers made at

Hull

By whom made

By whom made

sp "Stondo."

Hul. Rpt No 24990.

It is submitted, that the Hull Surveyors should be informed, that it is concluded that 8 man bearing botts have been fitted placed on board as spare, but as no mention is made of <sup>them</sup> in their report they should state whether this is so.

Lo: 15/5/12



© 2021

Lloyd's Register  
Foundation

W1470-0046

o. of Bilge Injections / sizes 22 Connected to condenser, or to circulating pump pump Is a separate Donkey Suction fitted in E  
re all the bilge suction pipes fitted with roses Yes Are the roses in Engine room always accessible Yes Are the sluices on Engine room  
re all connections with the sea direct on the skin of the ship Yes Are they Valves or Cocks Both

ort belonging

Is El

lers 3

as per rule 6

as fitted 4

after end of

liner does

on-corrosive

length of st

nk webs 4

le 20. Total

work

work

nnected to b

4

5