

Survey also  
the Report

Temporary repairs now effected by fitting a cement box in way of  
strake plate and overhauling the riveting and caulking

Class withdrawn by American Committee, per New York cable  
received 8.6.20.

for

VESSEL'S NAME

Steel S.S. "INGOLD"

Rpt.

Hul.

No 31853

W1474-0041

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.