

Date of writing Report.....19.....When handed in at Local Office.....19.....

on the <del>Wood, Iron or Steel</del> <i>ss. Kanapoi</i>		Master	YEAR.	MONTH.
<i>13</i>	<i>13</i>	<i>13</i>		

CROSS 2003 116 2 1/2 3 1/2 1/2 Port belonging to Shree duri

16217

<i>Surveyed Afloat or in Dry Dock?</i>	<i>Name of Deck</i>	<i>feet: f</i>	<i>feet:)</i>	<i>Particulars of Classification (which must be inserted)</i>
--	---------------------	----------------	---------------	---

B. All alterations in the existing records should be underlined.

Port *auk*  $\pm 100 \text{ A. I.}$   $\pm \text{LMC 1.11}$

Local Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent repairs. Repairs

esides being detailed in the body of the report, should be mentioned in the statement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the form. If there is any doubt as to the correctness of the particulars, the Officer should refer to the original documents and if necessary, to the original papers of the vessel. The Officer should also refer to the original papers of the vessel, and if necessary, to the original papers of the vessel, and if necessary, to the original papers of the vessel.

age cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were not accepted.

IPS OR EXAMINATION AS PER RULE, FOR .....

[illegible][illegible]

IT CONDITION OF THE	Inner Bottom Plating	Engine Room Skylights	When put on, Month.....Year.....
---------------------	----------------------	-----------------------	----------------------------------

State if Tanks now tested.....  
 Ballheads.....  
 Scuppers.....  
 Cargo Hatchways.....  
 Masts, Yards, &c.....  
 ....., has examined

Fastenings .....	Cement or Asphalt .....	Planking .....	of Wood Vessels .....	Sails .....
	(State which.)			

Steering gear and its connections.....	Treenails.....	ditto.....	Anchors, No. of.....
Windlass.....	Breasthooks & Stems.....	ditto.....	

cient?	Timbers of Frame at openings ditto	" length size (on board)
--------	------------------------------------	-----------------------------

Have Watertight Doors now been examined and found

*General Observations Opinion as to Class. Recommendation, &c.:*—

this survey, thus for example:—".....to remain as now classed in the Register Book *without* from record of survey, survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of *ss No. 1-15* and *ptND15, &c.*"

*[Faint, illegible markings]*

Special Damage or Repair Fee (if any) £

Surveyor to Lloyd's Register of Shipping.

*Committee's Minute* TUE. JUN. 1-1915

(The) Character Assigned Chief Clerk

W1482-0056

\_\_\_\_\_