

COPY.

Lloyd's Register of Shipping.



Port of HULL

19th March, 1942

This is to Certify that

W. S. SHIELDS

the undersigned Surveyor to this Society did at the request of

the Owners' Representatives attend on board the Steel Screw Steamer "CAPE CORSO", 3807 tons gross of Glasgow, whilst lying afloat and in dry dock in Alexandra Dock, Hull, on 9th February, 1942 and subsequent dates for the purpose of carrying out a General Examination for postponement of Special Survey 1st No. 3 which became due 8.41, for a period of twelve months.

An examination, as complete as practicable, was made of the holds, 'tween decks, bunkers (partly), and structure below the Boilers. The peaks, machinery spaces, decks, casings, ventilators, hatchways and closing appliances and general equipment were examined and the steering gear and its connections and windlass are in an efficient condition. Annual freeboard survey carried out at this time.

MACHINERY.

Examined propeller, cone end of screwshaft, main engines, circulating pump suction and delivery valves, dynamos and engines, fan engine, ballast pump, auxiliary feed pump, main & auxiliary condensers (tested), boilers complete, main and auxiliary engines generally, machinery tried under working conditions and found efficient.

REPAIRS.

Rudder lifted, pintles and bushes overhauled and streamline plate renewed. Renewed approximately about 1700 shell rivets and electric welded some 1000 shell rivets and a number of seams. No. 5 double bottom tank floors (4) fitted with angle bar stiffeners (as floor buckled). Bilgekeels part riveted. Three bulwark stays removed, faired and riveted. Fitted 17 brass plugs to main condenser. Renewed 50 tubes in auxiliary condenser. Renewed auxiliary boiler combustion chamber girder stays. Ballast pump water end renewed.

W. S. Shields

SURVEYOR TO LLOYD'S REGISTER OF SHIPPING

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."