

2 APR 1943

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "BANDAR SHAHPOUR" REPORT CTh. No. 3280

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The 2nd S.S.No.1 due 2.41.

A notation of "Examined 10.42" valid for 12 months has been assigned.

For conditions of class see endorsement 11.11.42.

The CAPE TOWN Surveyors report (12.42) the vessel examined afloat on account of damage through striking quay wall & stem & stem plating buckled, temporary repairs effected with cement. The Surveyors recommend permanent repairs at the first opportunity.

On account of damage during heavy weather repairs effected to wash port door.

IT IS SUBMITTED the vessel is worthy to remain as classed, subject as now recommended and as above.

As now, subject etc.



B.M.

2-11-43
© 2020Lloyd's Register
Foundation

WISO-0202