

1

Sent to Chief Surveyors 10.6.15.

Received from Chief Surveyors _____

VESSEL'S NAME ex "Linares" Report Low. No. 77865. b.**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Annual Survey When due 10.14

The first annual survey of this vessel's oil engines became due in 10.14.

The Owners now state that the vessel being under the Brazilian flag has to undergo a Government survey & they consider it better not to hold the annual survey in addition.

It is submitted that the vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof.

Withdraw class.

Insert . . .

JWD
10/6/15

A FRK



© 2021

Lloyd's Register
Foundation

W1516-0072