

1

Sent to Chief Surveyors 18.9.13

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME St K Maggie Gault Report Lon No. 76007<sup>a</sup>

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Screw shaft.

When due 5-12.

The screw shaft became due for survey in May 1912

The owner now states that he does not require the vessel's class

Submitted the vessel's class, he withdrew from the Register Book & 3 dots inserted in lieu thereof indicating withdrawal at owner's request.

Withdraw class  
Insert . . .

S. J. S. JWD  
18.9.13

C. J.

J. R. K.



© 2020

Lloyd's Register  
Foundation

W-1519-0014