

damage and it is recommended same be made good

30 SEP 1912

by Chief Ship Surveyor

Received from Chief Ship Surveyor

EL'S NAME Steel S.S. "ARLETTE" Rpt. Msl. No. 5410

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

The Marseilles Surveyors report this vessel has sustained slight damage to forecastle side plating, bulwarks etc. through collision.

No repairs have been effected and it is recommended this should be done at the Owners' convenience.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended.

As un. subject

Largobatter not fitted.



© 2019

Lloyd's Register Foundation

29. 9. 21.

W152-0044

Surveyor to Lloyd's Register of