

Do. of Houses on Deck... stern post... By whom built...
Do. of excess of Hatchways

Lloyd's Register of British & Foreign Shipping.

SURVEYOR'S OFFICE AMSTERDAM.

AMSTERDAM & VEENDAM DISTRICTS

J. B. SLEBE,
ENGINEER & SHIP SURVEYOR
NASSAUKADE 167.

TELEFOON No. 3895.

**M

LLOYDS REGISTER
LONDON.
RECEIVED SEP 1911
ANSP

Amsterdam, 4 of September 1911

The Secretary

LONDON

SIR

With reference to Your letter (classing-) of the 1 instant res-
pecting the Fee due on the machinery of the Hopper Dredger Maranhao, report
No 493I, which is stated not to have been received by the Society's NEWCAST-
LESurveyors.

From the enclosed letter received from Mr WARDROPPER You will observe
that it has been paid as well as the remainder of the Fee as advised to me
by Secretary's letter of the 3 of august which is also enclosed for Your
Information.

Kindly return the letters at Your earliest convenience and to forward the
Certificates of class which are urgently required

I Am, SIR

Your Obedient Servant

J. B. Slebe.



© 2021

Lloyd's Register
Foundation

WIS21-0056

Spacing
BEAMS, Second Deck, Single Angle, Bulbs

Angles on ditto, No.

Referred to the Chief Ship Surgeon
and the Chief Engineer Surveyor.

Referred to Mr. [Signature]
Referred to Mr. Wood

Urgent SEP - 5 1911

*Certs on Hull & Machinery forwarded
to by Messrs. J.G. & Co.
also the 2 address books.*

URGENT

SEP 5 1911



© 2021
Lloyd's Register
Foundation

Do. of Fort
Do. of Hon
Do. of ex...