

27.3 17.

Ed so. Manipur

Report

Cal

No. 3327

re to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case." — *Extract from Sub-Committee's Report 245/92.*

No. 2.

SURVEY PARTLY HELD.

L. 14

When proposed to be completed

P.S. due 7.15

T.S. " 11. 15

1d. The machinery survey has been held.

The case has been deferred from time to time, the
ing on Government service; and the Liverpool Surveyors
she is still so engaged.

The year of grace expired in January 1915.

The case is therefore submitted for the consideration
committee.

Therefore submitted for the consideration

27 : 3. 17

To complete the Survey:- In Nos. 2 & 4 tanks the
 attachments of floors & tank top to be examined & repaired
 the hold pillars (particularly under those pillars in the
 of the hatch) .

The middle frame- repaired by Oxy-acetylene process
ber 1912- to be examined at next dry docking.

Order Survey again requires to be held &
shaft examined

Lloyd's Register
Foundation

W1525-0211