

Wine

Chief Ship Surveyor 6.5.09

Received from Chief Ship Surveyor

NAME Ste. S. S. "Mallina"

Rpt. Bel.

No. 6605

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

First entry

It is submitted that before this can receive the consideration of the Committee the Surveyor should be requested by wire to state whether this vessel is fitted with cargo battens. A reply by wire should be requested.

Tel. No. 6/5709.

OK
6/5709



© 2020

Lloyd's Register
Foundation

W 1529-0086