

Received by Chief Ship Surveyor 11/107

Received from Chief Ship Surveyor

VESSEL'S NAME S.S. Trawler "Merlin" Rpt. Sub No. 18610

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	$\frac{9}{16}$ in lieu of $\frac{7}{32}$	Not required
Spar Sheerstrake . .	✓	✓
Description of Framing:— Ordinary, increased to compensate for (viz., ordinary, deep, zed, channel or bulb-angle). omission of wave frames.		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

+ 100 A-1 (Std) "Steam Trawler" as recommended.

+ 100 A-1 (Std) "Steam Trawler"

18"

11 B = D.T + 23' H2E

B.A 7 $\frac{1}{2}$ " S.B.A. Gen. Lloyds A & C.P



© 2021
RBN

11/107
Lloyd's Register
Foundation

W1531-0110