

Material of shell plates

Steel Thickness

32

Range of tensile strength

28-32

Are the shell

(Received at London Office

19

963.

Port

Middlesbrough.

Date

Mar. 24. 1914.

We

request that the

Donkey.

Boiler numbered as below to be made

Richardson Duck & Co. by

RILEY BROS. (BOILERMAKERS) LTD.

be Specially Surveyed while building.

We

hereby engage to pay Special Survey Fees as follows, viz. :—

For boilers up to 200 Nominal Horse Power, one shilling per Horse Power. For boilers over 200 Nominal Horse Power, one shilling per Horse Power for the first 200 Horse Power and fourpence per Horse Power above 200. The Nominal Horse Power to be reckoned at 15 square feet of heating surface. No fee to be less than £2 2s.

MEM.—In exceptional cases an additional charge will be made according to the services performed, and in all cases where travelling expenses are incurred by the Surveyors in connexion with the above services, they are to be defrayed by the parties interested.

Order No.

4730.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of British Foreign Shipping, which provide that :—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

FOR RILEY BROS. (BOILERMAKERS) LTD.

Signature

the Secretary,

Lloyd's Register of British and Foreign Shipping.

71, Fenchurch Street, London, E.C.

Lloyd's Register Foundation

NO. 963. ATTACHED.

W1535-0082