

Stk. S.S. "D" concern

To complete survey: Fore peak chain
locker cross bunker and after peak to
be examined. Some frames in
E & R spaces require to be repaired

W.H.W.

To complete the survey on Machinery
The whole of the Engines except the
Screw Shaft & Sea connections require
to be examined.

ARR
2.7.15



© 2021

Lloyd's Register
Foundation

W1550-0217