

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

-7 SEP 1923

VESSEL'S NAME Wood Sc. "LADY CORDEAUX"

Report Lon.

No. 86929

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey _____

When due _____

This vessel was built in 1922.

The New York Surveyors now forward a letter received from the Owners, in which they state that as the vessel carries no insurance, it is not necessary to undergo the expense of a further survey at present.

It is submitted the vessel's class be withdrawn from the Register Book and three dots inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...

CMS *BH*



© 2020

Lloyd's Register
Foundation

5.9.23.

W1556-0034