



Lloyd's Register of Shipping.

Collingwood Buildings, Newcastle-on-Tyne.

LLOYD'S REGISTER.
LONDON.

REC'D 19 FEB 1922

8th FEB 1922

Reference

ANSO Secretary.

Sir,

In reply to questions in
classing letter of 3rd Feb. 1922 regarding 1st Entry
Report on "City of Pittsburg" I have to state that
the 2nd deck stringer angle is 4x4x.50 as
approved & that the rivetting of poop side plating
is in accordance with the Rules.

With regard to the transverse plates at the level
of the stringers on bulkheads 124 & 158 I have
to explain that the indication of these on the
approved profile was interpreted as showing
brackets to bulkheads & stringers both by the builders
and myself, and horizontal plates extending
across the bulkhead have not been fitted.

I am, Sir,

Your obedient Servant,
G. Brown



Lloyd's Register
Foundation

W157-0122

1000 10 86

Referred to the Chief Ship Surveyor.

W.A.

-9 FEB 1922

W.A.

W.A.



© 2020

Lloyd's Register
Foundation



RAMS, R

ence

Rigged ...