

Glasgow Rpt 41698
T/S "Chilka"



SPARE GEAR.

T.S. "CHILKA" - No. 885.

- ✓ 2 bolts and nuts (or studs and nuts) for each size of rotor bearing.
- ✓ 2 bolts and nuts (or studs and nuts) main gear wheel bearing.
- ✓ 2 bolts and nuts (or studs and nuts) pinion bearing.
- ✓ 1 set of coupling bolts of each size used.
- ✓ One-twentieth of total number of bolts and nuts (or studs and nuts) for each gear case joints.
- ✓ One-twentieth of total number for each turbine casing joint.
- ✓ 2 thermometers for oil circulating system.
- ✓ 1 set of bearing bushes for one gear wheel shaft.
- ✓ 1 set of bearing bushes for rotor.
- ✓ 1 set of bearing bushes for pinion shafts.
- ✓ One half set of packing rings or segments for each gland of rotor shafts so fitted, and half the number of springs fitted.
- ✓ 2 ordinary thrust horseshoes (or thrust rings) for main thrust blocks, or sufficient pads for one face of Michell type of main thrust block.
- ✓ Turbine thrust and adjusting bushes with rings complete, or one set of pads of Michell type for one turbine of each size fitted.
- ✓ 1 set of liners for adjusting block, of different thicknesses.
- 1 air pump head valve, complete.
- 1 air pump bucket and rod.
- 1 circulating pump impeller and spindle.
- 1 set valves for air pump.
- 1 boiler check valve.
- ✓ 1 set of valve and seats for each size of pump.
- 20 condenser tubes.
- 100 sets of condenser tube packing.
- 50 glands for condenser tube packing.
- ✓ 1 spring for each size of escape valve.
- 3 safety valve springs, two for main and one for winch boilers.
- 20 common tubes for main boiler.
- 6 common tubes for winch boiler.
- 4 dozen gauge glasses for main and 6 for winch boilers.
- ✓ 3 iron plates, assorted.
- ✓ 6 iron bars, assorted.
- ✓ 100 assorted black bolts and nuts, with washers.
- ✓ 12 brass bolts and nuts, assorted, turned and fitted.
- ✓ 50 iron bolts and nuts, assorted, turned and fitted.

W158-0023 (1/2)



Spare Gear, Contd.

T.S. "CHILKA" - No. 885.

- 1 propeller shaft.
- 2 propeller blades, bronze, one right and one left-handed.
- 2 manhole door studs.
- 1 spare set of propeller boss studs and nuts for one blade only.
- 1 set of plain fire bars to be added for 1 main boiler.
- 1 half-set " " " " " " " Winch boiler.



WIS'8-0023 (2/2)



© 2020

Lloyd's Register
Foundation