

1.

Sent to Chief Surveyors

9/3/06

Received from Chief Surveyors

VESSEL'S NAME

St S. Seacombe

Report

No. 68137a

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

The S.S.No.1 became due in December 1905.

The Owners Superintendent now states in reply to enquiry that it has been decided not to continue the class in the Society's Register.

It is submitted the vessel's class be withdrawn from the Register Book, and three dots inserted in lieu thereof, indicating withdrawal of class at Owners request.

Withdraw class.

Insert (...).

RBA

9/3/06

C.S.

Ind

9.3.06

9.3.06

© 2021



Lloyd's Register Foundation

WIS84 - 0203