

Barcelona

Calle Mallorca 259

May 1918

Secretary  
London

RECEIVED MAY 29 1918

ANSW X

Dear Sir

In reply to your enquiry contained in the Claring letter of the 14<sup>th</sup> inst respecting the plating of the Steam hauler Montserrat. II it was not considered necessary to drill the shell plating as examined internally and externally it was found in good condition — There are no side lights fitted

I have advised the owners Sociedad Anonima Industrials of San Sebastian that the water tight bulkhead must be restored to enable the vessel to retain her class.

I am Dear Sir

Yours faithfully

Albert Weston



© 2020

Lloyd's Register  
Foundation

W1588-0152



Referred to the Chief Ship Surveyor.

Also for Mr. S. A. Hill to note.

29 5-18  
M

Referred to the Chief Ship Surveyor.

© 2020

Lloyd's Register  
Foundation