

Port of HULL.

4th May, 19 27.

REPORT ON MASTS, SPARS, AND RIGGING.

Men,

Having, in accordance with your instructions, examined
Masts, Spars, and Rigging, and Iron Work of same, of the
S.S. "LEPANTO",

I report that I found

MAST. Fore Stay to renew.

Service on shrouds and backstays to strip and reserve.

Port and Starboard.

in lower ends of rigging screws to renew.

LOCK TOWERS (AMIDSHIP). Guys on each to renew (3 each side).

M. 4 after guys to renew.

MAST. Service on shrouds and backstays to strip and reserve.

(Port and Starboard).

Starboard after shroud to renew.

Bolts in lower ends of rigging screws to renew.

Main Tomast to renew.

No mast wedges. With above exceptions everything found in
condition.

William Broughton

£ 10 0.

Surveyors,
Lloyd's Register of Shipping,

HULL.



© 2021

Lloyd's Register

Established 1780

34,