

For the information of Surveyors and the Committee only.

Received at _____ Office, _____ 19__

Lloyd's Register of Shipping.

(Report on Machinery, No. _____ Port _____)

13487 ENGINE FORGINGS OR CASTINGS.

I report that the Forgings or Castings, as herein described, manufactured
Messrs H Hingley & Sons of Lethbridge
the Engines No. _____ being repaired by Messrs Earle & Co
Hull for the Ship No. _____, being built by
S.S. "Zepherus" of _____

been inspected by me as set forth below, and found to be, so far as can
seen, sound and free from defects. These have been despatched to

or Castings.



J P Ringle

Sheffield 27/6/27

Screw Shaft - Int.

CRANK SHAFT.

THRUST SHAFT.

INTERMEDIATE SHAFT.

TUBE SHAFT.

FLYWHEEL SHAFT.

SCREW SHAFT.

Siemens Steel

Forged

Yes

15 3/8

Rough

Line-1127

Line-1126

30.6

30.92

35.0

35.0

180°

180°

2/6/27 to 8/6/27

PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS:-

shaft was examined before & after fitting
in various lines & found satisfactory.

LLOYDS.
No. 269.
J.K.W.
12/7/27.


chargeable) £3 - 3 - 0 To be paid at Sheffield

ht iron, state whether piled bars or scrap. If of steel, state whether made by the Open Hearth process.

Minute

+ L M D D. 9W

© 2021



Lloyd's Register
Foundation

for to L