

C. Lepanto.

Stul. 38334

submitted that before this case receives
decision, the Report should be returned
Surveyors for the signature of the
local Engineers, & that the Surveyors be
requested to state, (if the cables are correctly
identified as "Multicore") the number of
in each cable.

J.S.A.

16/9/27

Lloyd's Register
Foundation

X159-0077