

Wood. twin Sc. "Antofogasta." No Rpt 694.

The class of this vessel was expunged with a red line in 9. 22 on account of the watertube boiler survey, which became due in 6. 21 not being held or arranged for.

The screw shafts, which are fitted with continuous liners, became due for Examination in 6. 23.

All the machinery & the boilers, except the screw shafts, propellers & ~~and~~ sea connections have now been examined at Valparaiso & satisfactorily reported upon.

The Surveyor at Valparaiso states that the vessel will be dry docked at Talcahuano in the early part of February next.

It is submitted whether the vessel's class might not now be reinstated & the record of 35 9. 22 assigned. The record of LMC 9. 22 being referred until the screw shafts, propellers & sea connections have been examined, & subject to this being done in February 1923.

was held
class was expunged.



© 2021

J.W.

4/11/27

Lloyd's Register
Foundation

W1590-0017 018

W1590-0019