

18c.1210.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Wood Sc. Drifter "ICEBLINK" Rpt. Abn. No. 12388.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1st Entry

The weight of the 1st Bower Anchor is slightly less than that approved, but the collective weight is in excess of approved weight.

Anchors & Cables, supplied by Admiralty, tested as required but no certificates produced.

It is submitted the vessel appears worthy to be classed as 11A.1. "For Fishing Purposes" as recommended, and as follows:-

9 years Table A.

2 years, mixed materials

* 11A.1. "For Fishing Purposes"

9 & 12 years max.

1 Dk. Lloyds A & C.P.



© 2021

Lloyd's Register
Foundation

W1592-0162