

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London...  
No. in Reg. Book. Survey held at Date, First Survey Last Survey 19...  
13427 on the Wood, Iron or Steel Sc Sr "Bucovina" Master

TONNAGE:- Built at Trieste By whom Lloyd Austraco When 1902 3  
GROSS 2926 Owners Lloyd Triestino Port belonging to Trieste.  
UNDER DK. 2282 Owners' Address  
NET 1671 (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage  
WB=CellDBorDBa feet; uE&B feet; f feet; }  
total capacity tons. FPT tons; APT tons; MT feet tons. }  
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.  
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.  
Last Report, No. 5851 Port Tri.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)  
CHARACTER, for Special Survey, Date of last Survey and of Periodical Surveys.  
Year Assigned, if any, and Date of expiry.  
Machinery and Boiler Survey (including date of N.B., if any).  
+100A1 Spandk 5.23  
+LMC1221 BS1022  
SS Tri No 3-4, 14.  
SS Tri No 2-21.  
Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

RETAIN

SUMMARY OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed ... ..								
Removed and Fair'd or Repaired ... ..								
Fair'd or Repaired in place ... ..								

PRESENT CONDITION OF THE								
Decks	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels					
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt.)					
Waterways	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month					
Coamings	Ceiling	Scuppers	Boats					
Beams & Fastenings	Cement or Asphalt (State which.)	Cargo Hatchways	Masts, Yards, &c.					
Outside Plating	Rudder	Hatches	Condition, how ascertained					
Caulking of ditto	Steering gear and its connections	Planking of Wood Vessels	(State if wedges removed)					
Rivets	Windlass	Caulking ditto	Sails					
Breasthooks & Crutches	Have Pumps now been examined and found efficient?	Treenails ditto	Equipment letter					
Transoms	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. of					
Frames	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)					
Reverse Frames	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	length size					
Floors		Ditto ditto at other places ditto	(on board) Rule length size					
Keelsons		Stringers, Clamps & Shelves ditto	Hawser & Warps					
Stringers		Salting (State if examined.) ditto	Standing & Running Rigging					
Inner Bottom Plating								

General Observations, Opinion as to Class, Recommendation, &c.:—  
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Survey Fee (per Section 20)	£	:	:	Fees applied for,	
Special Damage or Repair Fee (if any) (per Sec. 20)	£	:	:	19	
Travelling Expenses (if chargeable)	£	:	:	Received by me,	
Second Surveyor's Fee (if any)	£	:	:	19	

Committee's Minute  
Character Assigned

Surveyor to Lloyd's Register of Shipping.  
Lloyd's Register Foundation

W1599-0200