

Chief Surveyors

Received from Chief Surveyors

SHIP'S NAME

S.S. Vesta

Report

Ln

No. 86446^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

Screwshaft

When due

~~7.23~~ 7.22.

The screwshaft became due for survey in July last.

The Grimsby Surveyors now state they are informed by the Owners that in order to keep this vessel in conformity with their others they desire the class to be withdrawn.

Submitted that the vessels class be withdrawn from the Register Book & three dots (...) inserted in lieu thereof indicating withdrawal of class at Owners request.

Withdraw class
Insert (...)

M 16 3



© 2021

Lloyd's Register
Foundation

W604-0167