

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

Don Esteban

Rpt.

*Ma. 2671**2672*

Marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Endorsement

Survey

~~SPECIAL SURVEY OF ENGINES AND/OR BOILERS PARTLY HELD FOR S.S. No.~~

LMC

LMC(M) due

MS

ES

, partly held

C.S.

now further advanced and the following repairs effected (due to *damage through broken crank shaft*)

Temporary repairs to starboard main crank shaft.

~~It is proposed to complete the survey~~

It is submitted that ~~this proposal merits approval~~ and the vessel is eligible to remain as classed, and WILL BE eligible for the record ~~reclass date~~ when the survey has been completed.

The following remains to be done to complete the Survey

See Form 7E

Subject to the application of starboard main crank shaft being renewed before the end of 2-39



© 2020

Lloyd's Register Foundation

W161-0017