




© 2020

Lloyd's Register
Foundation

M. S. Don Esteban

Picture of broken Journal N86
Starb. Main Engine Crankshaft.



W161-0124