

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book. Survey held at Date, First Survey Last Survey 19

34419 on the Wood, Iron or Steel Ssk Vidonia Master

TONNAGE:- Built at Selby By whom Buchanan & Son When 20th 5th

GROSS 276 Owners Lindsay Steam Fishing Co Ltd Port belonging to Lindsay

UNDER DK 26 Owners' Address (if not already recorded in Appendix to Register Book)

NET 124

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; }

total capacity tons. APT tons; APT tons; APT tons; APT tons; }

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 11884 Port Gms

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER, No. for Special Survey, Date of last Survey and of Periodical Surveys.

Years Assigned and expired.

Machinery and Boiler Surveys (including date of N.B., if any).

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

| SUMMARY OF DAMAGE REPAIRS:— | Plates. | Frames. | R. Frames. | Floors. | Beams. | Str. Plates. | Dk. Plates. | Other Items:— |
|------------------------------------|---------|---------|------------|---------|--------|--------------|-------------|---------------|
| Renewed ... | | | | | | | | |
| Removed and Faired or Repaired ... | | | | | | | | |
| Faired or Repaired in place ... | | | | | | | | |

| PRESENT CONDITION OF THE | | | | | | | | |
|--------------------------|--|--------------------------------------|---------------------------------|--|--|--|--|--|
| Decks | State if Tanks have been examined inside | Dblng. Plates under Sounding Pipes | Copper, or Y.M. of Wood Vessels | | | | | |
| Caulking of Decks | State if Tanks now tested | Engine Room Skylights | (State if on Fell.) | | | | | |
| Waterways | Bulkheads | Coal Bunkers, Open'gs, Lids, &c. | When put on, Month | | | | | |
| Coamings | Ceiling | Scuppers | Boats | | | | | |
| Beams & Fastenings | Cement or Asphalt (State which.) | Cargo Hatchways | Masts, Yards, &c. | | | | | |
| Outside Plating | Rudder | Hatches | Condition, how ascertained | | | | | |
| Caulking of ditto | Steering gear and its connections | Planking of Wood Vessels | (State if wedges removed) | | | | | |
| Rivets | Windlass | Caulking ditto | Sails | | | | | |
| Breasthooks & Crutches | Have Pumps now been examined and found efficient? | Treenails ditto | Equipment letter | | | | | |
| Transoms | Have Sluice Valves now been examined and found efficient? | Breasthooks & Stemson ditto | Anchors, No. o | | | | | |
| Frames | Have Watertight Doors now been examined and found efficient? | Transoms, Pointers, & Crutches ditto | Cables (State if now ranged) | | | | | |
| Reverse Frames | Have Ventilators and their Coamings been examined and found efficient? | Timbers of Frame at openings ditto | „ length size | | | | | |
| Floors | | Ditto ditto at other places ditto | „ Rule length size | | | | | |
| Keelsons | | Stringers, Clamps & Shells ditto | Hawser & Warps | | | | | |
| Stringers | | Salting ditto | Standing & Running Rigging | | | | | |
| Inner Bottom Plating | | (State if examined.) | | | | | | |

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—“to remain as now classed in the Register Book without fresh record of Survey,” “to remain as classed and to have record of survey, 1,15,” or “to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and pND15, &c.”

| | | | |
|--|---|---|-------------------|
| Survey Fee (per Section 28) ...£ | : | : | Fees applied for, |
| Special Damage or Repair Fee (if any) (per Sec. 29) ...£ | : | : | 19... |
| Travelling Expenses (if chargeable) ...£ | : | : | Received by me, |
| Second Surveyor's Fee (if any) ...£ | : | : | 19... |

Committee's Minute TUE. 13 DEC 1921

Character Assigned Withdraw class

Surveyor to Lloyd's Register of Shipping

Special General Committee

Thursday, 15th December, 1921

Lloyd's Register

Classing Committee's

decision confirmed

W1611-0152