

Received by Chief Ship Surveyor 14-12-14 Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Steel Liner "Buyak Ada" Rpt. \_\_\_\_\_ No. \_\_\_\_\_

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 39.25 Depth "d" 10.25

Framing: Table No. ✓ Description ✓

Longitudinal No. 7693

Proportions  $\frac{\text{Length}}{\text{Depth}} = \frac{17.4}{10.25}$

~~Deck~~ Sheerstrake & other scantlings as approved  
for the A-1. class

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed A-1 (Steel) for service on the Bosphorus & Sea of Marmara as recommended.

A-1 (Steel) for service on the Bosphorus & Sea of Marmara  
10.14 Wm  
1 Dr  
FK. SBN. Cam. Lloyd's arcp.  
Date of Build 8.14

*E. L. L.*  
© 2021



Lloyd's Register  
Foundation