

VESSEL'S NAME

S. S. Galicia

Report

Tri

No.

718

Remarks of the CHIEF ENGINEER SURVEYOR for the consideration of the Classing Committee.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First Entry.

If only partially held, the Committee require in each case a brief statement of the following, amongst other particulars:—

When Survey became due

When proposed to be completed

Remarks:—

It is submitted that  
this vessel is eligible for

THE RECORD.

+ LMC 6.02. FD

Elec. light.

C.M.

19.6.02

The Surveyor should be requested to state if the screw shaft is fitted with a continuous liner, two separate liners, or two liners with a burnt joint, also the length of the sternbush.

The donkey boiler's plan should be returned as requested to the Surveyor.

C.M.

20/6/02

W1517-6090

advised in  
L. Plan  
P. Post  
20/6/02

Lloyd's Register  
Foundation