

to Chief Surveyors 9.4.15.

Received from Chief Surveyors _____

VESSEL'S NAME Stl.S.S. "YU SANG".

Report Shi.

No 1510a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Nature of Survey _____


When due _____

The Dairen Surveyor reported in February last that this vessel had sustained damage to the topside plating &c., through collision. Temporary repairs were effected and it was proposed to effect permanent repairs on the vessel's arrival at Shanghai.

The Shanghai Surveyor now states he is informed by the Owners that they do not wish to maintain the vessel's class.

It is submitted the vessel's class be omitted from the reprint of the Register Book.

M. M. 15
19.
Sw
E. 12



©2021

Lloyd's Register
Foundation