

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Rpt.

No. 25136

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

Depth "d"

Framing: Table No.

Description

Longitudinal No.

Proportions

Length

Depth =

Bridge Deck Sheerstrake

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \pm 100A1. (Stub) as recommended.

\pm 100A1 (Stub)

/ Dr (24-115) 25 B

1713. Cull 2 Ba 75 u 343 35 7119 4291 FPTHIC APT HOC
FK H.B.H. Cmn. Lloyd's at 60 P 11 370 F81



© 2021

Lloyd's Register Foundation

W1618-0094