

COPY.

Lloyd's Register of Shipping.



Port of EAST LONDON, SOUTH AFRICA.

11th July, 1942.

This is to Certify that I have

Surveyed the ~~Boiler and~~ ^{Part} Machinery of the British Twin Screw Motor Vessel "DANMARK" 8391 tons gross of Liverpool, for Part Continuous Survey,

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have Recommended that the record of L M C C S 7, 42.

(In red)

be made in the Register Book in the case of this vessel when the survey has been completed.

Parts now examined:— No. 2 Starboard Main Engine, Piston, Cylinder liner, Cross head, Top and bottom end bearings, 4 new piston rings fitted.
No. 5 Starboard Main Engine, Piston, Cylinder liner, Crosshead, Top and bottom end bearings, new piston rings fitted.
No. 3 Port Main Engine, Piston, Cylinder liner, Crosshead, Top and bottom end bearings, new piston rings fitted.
No. 5 Port Main Engine, Piston, Cylinder liner, Crosshead, Top and bottom end bearings, new piston rings fitted.
No. 3 Generator, H.P. Compressor piston rings renewed. I.P. compressor, 4 piston rings renewed. L.P. Compressor, 2 piston rings renewed. New rings fitted to both Engine pistons, (2.Cylinder) New gudgeon pins fitted to after piston. After bottom end bearings re-metalled.
New keyways fitted on Camshafts of both Main Engines.
No. 1 Auxiliary complete. No. 3 Auxiliary complete.
Port & Starboard starting air receivers seen internally & externally with fittings. 2 Spare injection air receivers with fittings.

Engineer Surveyor to Lloyd's Register.

(signed) G. D. Macdonald, MARINE ENGINEER.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."