

Do.
Do.
Do.
Do.

(2m.1.6.)

1.

Sent to Chief Surveyors 9/8/06

Received from Chief Surveyors _____

VESSEL'S NAME SS "Luristan"

Report Sup No. 14791

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First entry

When due _____

+ 100A1 (Blue) Sparak
1 Dⁿ (2H) + Sparak (2H) + dup framing
WB - 600 D Ba + n to 134' + 156' 690t a P J 20t
JA 6 BA, Cum Lloyds at 60, 085 386' F 41'

C.F.
R.R.H.
10/6/06



© 2021

Lloyd's Register
Foundation

W1623-0084