

Carrying Petroleum in Bulk
SS "ANNE DE FRANCE"

Available records of the electrical
and cargo pumping arrangements
installation, are insufficient to enable the extent
of alterations necessary to bring ~~it~~ ^{the vessel} into conformity
with present day safety standards to be determined
and it will therefore be necessary for the *electrical*
and pumping arrangements
installation, to be specially examined at the next
suitable opportunity in accordance with Circular
No. 1994.

See endorsement dated 25.6.51.

S.O.

18th December, 1952. *lrc*

Ship Surveyors

*The midships accommodation situated on the
top of the cargo tanks should be separated
from the cargo below by a cofferdam*