

Chief Surveyors.....

Received from Chief Surveyors.....

EL'S NAME "EMPRESS OF CANADA" REPORT Liv. No. 136906

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey..... ~~XXXXXX~~

This vessel came under survey at Liverpool in 1,53 in dry dock for damage and commencement of Progressive S.S. due 2,56.

After the vessel undocked, and during repairs and advancement of the Progressive S.S., she sustained serious fire damage and now lies on her port side in Gladstone Dock, Liverpool with Salvage Authorities in occupation.



R.S.B.

26.2.53

Lloyd's Register
Foundation

W1625-0019