

2E
2- AUG 1949

by Chief Engineer Surveyor

Received from Chief Ship Surveyor

LS NAME "EARL KITCHENER" REPORT Hul. No. 55775

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey COMPLETION OF SPECIAL SURVEY OF ~~ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due 6.49 now held & the screwshaft examined now
partly completed,--and the following repairs carried out--(due to):-

It is submitted the vessel is eligible to remain as classed, with
notation of BS 6.49, S 6.49 as recommended.



© 2021

Lloyd's Register
Foundation

W1628-0016

29.7.49.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.