

Im. 2.32.

5E
11 DEC 1932

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Dartford

Rpt.

nwc

No.

89569

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Nature of Survey

~~DAMAGE & WEAR AND TEAR.~~

Superheaters now fitted to main boilers in accordance with the rules and machinery tested under working conditions satisfactory

Damage due to grounding examined found in order

Screw shaft & Condenser



© 2019

It is submitted the vessel is eligible to remain as classed with record of Survey S. 12.32 as recommended.

Lloyd's Register
Foundation

15.12.32

W163-0007