

5mrl.53

11 Apr 1953 4E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SHIP'S NAME

"LA SALINA"

REPORT Aru

No. 1528

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

Nature of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

This vessel has a notation of "Laid Up - Surveys Overdue".

A satisfactory General Examination of the engines and boilers now held with a view to the issue of a certificate, as for unclassed ships, for a voyage from Aruba to a Southern U.S. Port where the vessel is to lay up.

IT IS SUBMITTED no further action be taken pending receipt of further information regarding the vessel's ultimate disposal.



© 2021

30.4.53.

Lloyd's Register  
Foundation

W1633-0152