

Urgent.

Lloyd's Register of Shipping,

RECEIVED

21 AUG 1947

22/8

AND

Ocean Chambers, Lowgate,

Hull, 20th August, 1947.

s.s. "REYKJANES", ex "Empire Contay".

Dear Sir,

We beg to acknowledge the receipt of your two letters of the 17th and 18th instant, respecting the above vessel, and in reply have to inform you that the Owners decided they desired the figure "1" to be assigned and accordingly ordered 210 fathoms of 1-7/16" Chain Cable and three bower anchors of Rule size and weight to conform with the requirements of Equipment Letter "m". This equipment is now lying at Goole ready for placing on board upon the vessel's anticipated return at the end of this month.

In the meantime the equipment actually on board the vessel at present consists of three bower anchors and 195 fathoms of chain cable, which are not of a standard equivalent to that required by the Rules.

The replies to your enquiries concerning the hull of the vessel will be forwarded immediately Mr. Palmer returns from his leave of absence, at the beginning of next week.

Yours faithfully,

The Surveyors.

Per:-

McIntosh

Rule

m

= 210

2 7/16

The Secretary,

LONDON.

*3 Bows / Strain
anchors*



© 2021

Lloyd's Register
Foundation

Referred to Mr. ~~D~~ Slack

BAH

MS

RS



© 2021

Lloyd's Register
Foundation