

COPY

## Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

7th August, 1947.

s.s. "REYKJANES"  
 ex "Empire Contay".  
 -----


Dear Sirs,

With reference to your First Entry Report No. 54243 on the above vessel, I shall be glad if you will be good enough to state the spacing of the solid floors, the thickness of the tankside brackets, and to verify the breadth at bottom of the bracket floors at the margin plate.

At the same time I have to inform you it is concluded that the hatchways in the 2nd deck in way of the after hold are fitted with shifting beams and wood covers, but your confirmation on this point is requested.

I shall be glad if you will also forward particulars of the size and position of the bilge injection and the direct bilge suction to the ballast pump, and in this connection I have to refer you to my letter of the 3rd June.

Yours faithfully,


 pro Secretary.

 The Surveyors,  
 HULL.