

nt to Chief Surveyors _____

Received from Chief Surveyors _____

ESSEL'S NAME Sheells "Ampecto" Report Baltimore No. 2355

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

ature of Survey _____ When due _____

100A-1 (Steel) Shells DK with freeboard, carrying petroleum in bulk
 2 DKs (Steel) & Shells DK (Steel) & Webframes. Longitudinal Framing
 Cell DB a 88' 3516. D-T + 50 7246. F.P.T. 1756 A.P.T. 286.
 F.K. 18BH (14 to 40" & 2" dk) pl. cen. area. Mech. abt.

W164-0162

2. 7. 18

Shall ing.

Lloyd's Register
Foundation