


The scantlings of the boiler + shafting as shown
on the plans + stated in the Reports are
such as could be accepted.

W.B.

R.

J.W.B. 12/12/40.



© 2020

Lloyd's Register
Foundation

W16H2 - 0212