

A request has been received for a postponement of the Special Survey 12.53 and the Surveyors have recommended that the survey might be postponed until 12.53, so far as the Hull is concerned.

3 E

Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

NAME "ALLIAN" REPORT Hbg. No. 2337.

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

is endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and so to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points wanted in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

SPECIAL SURVEY OF ENGINES AND/OR BOILERS PARTLY HELD.

due 4.53 , partly held now and vessel examined on floating dock and satisfactory General Examination of machinery carried out.

~~Further advanced~~ and the following repairs effected (due to wear and tear

Some condenser tubes re-packed and others plugged. Some screw renewals in the main boiler and port and starboard combustion chambers found to be buckled. The Surveyor recommends they be specially examined and dealt with and the electrically welded repair to the main front end plate examined before the end of 12.53.

It is proposed to complete the survey at the first convenient opportunity.

It is submitted that this proposal merits approval and the vessel is eligible to remain as classed, and WILL BE eligible for the record

when the survey has been completed, subject as recommended and the proposal to postpone the Special Survey until 12,53 ~~the following remains to be done to complete the Survey~~ merits favourable consideration.

John

10.4.53.



© 2021

Lloyd's Register Foundation

W1643-032