

not checked..... Have machines over 100 kw. been inspected by the Surveyors during manufacture and testing.....

Empire Insurance

Mat 16896

The kilowatts of the dynamo amount to 30.

The I.E. fee for such an installation is £22-10/- or 35% of that sum, viz £7-17-6, is chargeable now

*BR*  
19/9/40

Lloyd's Register  
Foundation

WX65-0129

semi-insulating material (slate or marble) are all conducting parts insulated therefrom as per Rule..... Is the frame