

Week Section 202



Lloyd's Register of Shipping.

201, Tower Building,

Liverpool, 3. 4th October, 1938.

LLOYD'S REGISTER
Received
5 OCT 1938
Ansd.
LONDON

Reference

S.

Dear Sir,

With reference to your letter of the 3rd instant regarding the marks on the tail shaft recently fitted to the m.v. "HOEGH CARRIER" I have to state that when this Spare shaft was fitted no note was taken of the marks.

The Engineer informed the Surveyor that the shaft in question was the unused one placed on board as spare at the time the vessel was built.

I am, Dear Sir,

Yours faithfully,

The Secretary,
LONDON.



© 2019

Lloyd's Register
Foundation

W172-0077

opinion to remain as classed with fresh record of Carv

